

AZ1

73°51'1.117"W 41°0'34.826"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 15
 EASTING 671420.394
 FID 0
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 123.299
 GPS_TIME 07:24:46am
 HORZ_PREC 1.5
 HyI ..\data\photos\ARD-1A.JPG
 HyII ..\data\photos\ARD-1B.JPG
 Hyper ..\photos\ARD-1A.JPG
 HyperII ..\photos\ARD-1B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-1A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 3.5
 NORTHING 793383.109
 OUTFALL_DA No
 OUTFALL_ID ARD-1
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-1A.JPG
 PHOTO2 ARD-1B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.735005
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.2

AZ2

73°50'58.748"W 41°0'36.185"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 671602.443
 FID 1
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 128.377
 GPS_TIME 07:30:40am
 HORZ_PREC 1.7
 HyI ..\data\photos\ARD-2A.JPG
 HyII ..\data\photos\ARD-2B.JPG
 Hyper ..\photos\ARD-2A.JPG
 HyperII ..\photos\ARD-2B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-2A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 3.3
 NORTHING 793522.671
 OUTFALL_DA No
 OUTFALL_ID ARD-2
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-2A.JPG
 PHOTO2 ARD-2B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.197755
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 2.4

AZ3

73°50'58.818"W 41°0'37.085"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 12
 EASTING 671590.527
 FID 2
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 166.757
 GPS_TIME 07:36:03am
 HORZ_PREC 2.7
 HyI ..\data\photos\ARD-3A.JPG
 HyII ..\data\photos\ARD-3B.JPG
 Hyper ..\photos\ARD-3A.JPG
 HyperII ..\photos\ARD-3B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-3A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL Steel
 MAX_PDOP 9.1
 NORTHING 793616.865
 OUTFALL_DA No
 OUTFALL_ID ARD-3
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-3A.JPG
 PHOTO2 ARD-3B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV10.25709
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 0.8

AZ4

73°50'58.921"W 41°0'37.06"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS PUMP FROM AUTOBODY
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 4
 EASTING 671580.095
 FID 3
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 121.437
 GPS_TIME 07:37:47am
 HORZ_PREC 1.6
 HyI ..\data\photos\ARD-4A.JPG
 HyII ..\data\photos\ARD-4B.JPG
 Hyper ..\photos\ARD-4A.JPG
 HyperII ..\photos\ARD-4B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-4A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL PVC
 MAX_PDOP 3.2
 NORTHING 793617.865
 OUTFALL_DA No
 OUTFALL_ID ARD-4
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-4A.JPG
 PHOTO2 ARD-4B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.635141
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 2.3

AZ5

73°50'57.149"W 41°0'41.008"N
 ABNORMAL_V No
 CHARACTERI
 COMMENTS BLOCKED BY STONES
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 15
 EASTING 671718.469
 FID 4
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 122.579
 GPS_TIME 07:48:16am
 HORZ_PREC 1.4
 HyI ..\data\photos\ARD-5A.JPG
 HyII ..\data\photos\ARD-5B.JPG
 Hyper ..\photos\ARD-5A.JPG
 HyperII ..\photos\ARD-5B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-5A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL Steel
 MAX_PDOP 2.9
 NORTHING 794007.37
 OUTFALL_DA No
 OUTFALL_ID ARD-5
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-5A.JPG
 PHOTO2 ARD-5B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.684759
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 0.9

AZ6

73°50'56.399"W 41°0'42.415"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 48
 EASTING 671769.221
 FID 5
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 154.578
 GPS_TIME 07:55:44am
 HORZ_PREC 2.1
 HyI ..\data\photos\ARD-6A.JPG
 HyII ..\data\photos\ARD-6B.JPG
 Hyper ..\photos\ARD-6A.JPG
 HyperII ..\photos\ARD-6B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-6A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL CMP
 MAX_PDOP 6.8
 NORTHING 794157.05
 OUTFALL_DA No
 OUTFALL_ID ARD-6
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-6A.JPG
 PHOTO2 ARD-6B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV5.275022
 SUBMERGED Water Partially
 UPDATE_STA New
 VERT_PREC 1.2

AZ7

73°50'56.96"W 41°0'42.854"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 671725.135
 FID 6
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 136.803
 GPS_TIME 08:00:27am
 HORZ_PREC 4.9
 HyI ..\data\photos\ARD-7A.JPG
 HyII ..\data\photos\ARD-7B.JPG
 Hyper ..\photos\ARD-7A.JPG
 HyperII ..\photos\ARD-7B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-7A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 7
 NORTHING 794192.684
 OUTFALL_DA No
 OUTFALL_ID ARD-7
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-7A.JPG
 PHOTO2 ARD-7B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV5.169173
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.8

AZ8

73°50'56.162"W 41°0'43.461"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS OUTLET FROM PRIVATE BASIN
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 671792.66
 FID 7
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 148.206
 GPS_TIME 08:09:59am
 HORZ_PREC 1.1
 HyI ..\data\photos\ARD-8A.JPG
 HyII ..\data\photos\ARD-8B.JPG
 Hyper ..\photos\ARD-8A.JPG
 HyperII ..\photos\ARD-8B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-8A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 2.3
 NORTHING 794260.179
 OUTFALL_DA No
 OUTFALL_ID ARD-8
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-8A.JPG
 PHOTO2 ARD-8B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.407191
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.1

AZ9

73°50'55.642"W 41°0'44.397"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 15
 EASTING 671829.098
 FID 8
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 132.555
 GPS_TIME 08:19:19am
 HORZ_PREC 1.8
 HyI ..\data\photos\ARD-9A.JPG
 HyII ..\data\photos\ARD-9B.JPG
 Hyper ..\photos\ARD-9A.JPG
 HyperII ..\photos\ARD-9B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-9A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 3.8
 NORTHING 794345.493
 OUTFALL_DA No
 OUTFALL_ID ARD-9
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-9A.JPG
 PHOTO2 ARD-9B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.326493
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.4

AZ10

73°50'55.545"W 41°0'44.82"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS NOT ACCESSIBLE
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 36
 EASTING 671854.218
 FID 9
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 128.677
 GPS_TIME 08:22:17am
 HORZ_PREC 1.3
 HyI ..\data\photos\
 HyII ..\data\photos\
 Hyper ..\photos\
 HyperII ..\photos\
 Hyperlink
 LAND_USE_A Commercial
 Location
 MATERIAL CMP
 MAX_PDOP 2.8
 NORTHING 794382.892
 OUTFALL_DA No
 OUTFALL_ID ARD-10
 OUTFALL_TY Closed Pipe
 PHOTO1
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.71183
 SUBMERGED Water Partially
 UPDATE_STA New
 VERT_PREC 1.4

AZ11

73°50'55.127"W 41°0'45.102"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 48
 EASTING 671870.852
 FID 10
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 129.441
 GPS_TIME 08:24:58am
 HORZ_PREC 1.4
 HyI ..\data\photos\ARD-11A.JPG
 HyII ..\data\photos\ARD-11B.JPG
 Hyper ..\photos\ARD-11A.JPG
 HyperII ..\photos\ARD-11B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-11A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 2.9
 NORTHING 794426.705
 OUTFALL_DA No
 OUTFALL_ID ARD-11
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-11A.JPG
 PHOTO2 ARD-11B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.276794
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.9

AZ12

73°50'52.173"W 41°0'46.987"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS OUTLET FOR BASIN
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 30
 EASTING 672108.336
 FID 11
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 120.432
 GPS_TIME 08:32:35am
 HORZ_PREC 1
 HyI ..\data\photos\ARD-12A.JPG
 HyII ..\data\photos\ARD-12B.JPG
 Hyper ..\photos\ARD-12A.JPG
 HyperII ..\photos\ARD-12B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-12A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 2.3
 NORTHING 794608.499
 OUTFALL_DA No
 OUTFALL_ID ARD-12
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-12A.JPG
 PHOTO2 ARD-12B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.222549
 SUBMERGED Sediment Partially
 UPDATE_STA New
 VERT_PREC 1.1

AZ13

73°50'53.019"W 41°0'46.145"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS END OF PIPE NOT ACCESSIBLE
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 12
 EASTING 672053.421
 FID 12
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 131.487
 GPS_TIME 08:48:37am
 HORZ_PREC 1.5
 HyI ..\data\photos\ARD-13A.JPG
 HyII ..\data\photos\ARD-13B.JPG
 Hyper ..\photos\ARD-13A.JPG
 HyperII ..\photos\ARD-13B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-13A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL Steel
 MAX_PDOP 3.4
 NORTHING 794464.583
 OUTFALL_DA No
 OUTFALL_ID ARD-13
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-13A.JPG
 PHOTO2 ARD-13B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.508566
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.7

AZ14

73°50'51.037"W 41°0'46.751"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS GOES INTO DETENTION POND
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 672181.275
 FID 13
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 114.875
 GPS_TIME 08:55:15am
 HORZ_PREC 1.9
 HyI ..\data\photos\ARD-14A.JPG
 HyII ..\data\photos\ARD-14B.JPG
 Hyper ..\photos\ARD-14A.JPG
 HyperII ..\photos\ARD-14B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-14A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 9.1
 NORTHING 794597.409
 OUTFALL_DA No
 OUTFALL_ID ARD-14
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-14A.JPG
 PHOTO2 ARD-14B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV2.899523
 SUBMERGED Water Partially
 UPDATE_STA New
 VERT_PREC 1.3

AZ15

73°50'50.58"W 41°0'48.389"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS OUTLET FROM BASIN
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 30
 EASTING 672218.018
 FID 14
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 119.445
 GPS_TIME 08:59:47am
 HORZ_PREC 1.1
 HyI ..\data\photos\ARD-15A.JPG
 HyII ..\data\photos\ARD-15B.JPG
 Hyper ..\photos\ARD-15A.JPG
 HyperII ..\photos\ARD-15B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-15A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 3.1
 NORTHING 794768.443
 OUTFALL_DA No
 OUTFALL_ID ARD-15
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-15A.JPG
 PHOTO2 ARD-15B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.265573
 SUBMERGED Sediment Partially
 UPDATE_STA New
 VERT_PREC 1.8

AZ16

73°50'45.646"W 41°0'48.196"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 672598.155
 FID 15
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 135.047
 GPS_TIME 09:08:00am
 HORZ_PREC 1.2
 HyI ..\data\photos\ARD-16A.JPG
 HyII ..\data\photos\ARD-16B.JPG
 Hyper ..\photos\ARD-16A.JPG
 HyperII ..\photos\ARD-16B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-16A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 1.4
 NORTHING 794746.618
 OUTFALL_DA No
 OUTFALL_ID ARD-16
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-16A.JPG
 PHOTO2 ARD-16B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.52618
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1

AZ17

73°50'45.509"W 41°0'48.366"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS NYC AQUADUCT BLOWOFF
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 60
 EASTING 672606.758
 FID 16
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 137.034
 GPS_TIME 09:09:25am
 HORZ_PREC 1.2
 HyI ..\data\photos\ARD-17A.JPG
 HyII ..\data\photos\ARD-17B.JPG
 Hyper ..\photos\ARD-17A.JPG
 HyperII ..\photos\ARD-17B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-17A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 3.3
 NORTHING 794763.401
 OUTFALL_DA No
 OUTFALL_ID ARD-17
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-17A.JPG
 PHOTO2 ARD-17B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.433969
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 2.2

AZ18

73°50'45.404"W 41°0'48.879"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 672605.6
 FID 17
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 135.206
 GPS_TIME 09:11:19am
 HORZ_PREC 1.5
 HyI ..\data\photos\ARD-18A.JPG
 HyII ..\data\photos\ARD-18B.JPG
 Hyper ..\photos\ARD-18A.JPG
 HyperII ..\photos\ARD-18B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-18A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 5.8
 NORTHING 794798.601
 OUTFALL_DA No
 OUTFALL_ID ARD-18
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-18A.JPG
 PHOTO2 ARD-18B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.410588
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 3.3

AZ19

73°50'44.179"W 41°0'50.03"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 672704.076
 FID 18
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 138.638
 GPS_TIME 09:18:43am
 HORZ_PREC 1.3
 HyI ..\data\photos\ARD-19A.JPG
 HyII ..\data\photos\ARD-19B.JPG
 Hyper ..\photos\ARD-19A.JPG
 HyperII ..\photos\ARD-19B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-19A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 4.3
 NORTHING 794934.981
 OUTFALL_DA No
 OUTFALL_ID ARD-19
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-19A.JPG
 PHOTO2 ARD-19B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.822466
 SUBMERGED Sediment Partially
 UPDATE_STA New
 VERT_PREC 2.7

AZ20

73°50'48.74"W 41°0'53.551"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 30
 EASTING 672339.806
 FID 19
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 121.304
 GPS_TIME 09:24:07am
 HORZ_PREC 1.2
 HyI ..\data\photos\ARD-20A.JPG
 HyII ..\data\photos\ARD-20B.JPG
 Hyper ..\photos\ARD-20A.JPG
 HyperII ..\photos\ARD-20B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-20A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 4.6
 NORTHING 795280.343
 OUTFALL_DA No
 OUTFALL_ID ARD-20
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-20A.JPG
 PHOTO2 ARD-20B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.802157
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.3

AZ21

73°50'46.424"W 41°1'1.75"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 4X4X2
 EASTING 672533.183
 FID 20
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 123.968
 GPS_TIME 09:34:09am
 HORZ_PREC 1.3
 HyI ..\data\photos\ARD-21A.JPG
 HyII ..\data\photos\ARD-21B.JPG
 Hyper ..\photos\ARD-21A.JPG
 HyperII ..\photos\ARD-21B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-21A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL Earthen
 MAX_PDOP 4.6
 NORTHING 796111.106
 OUTFALL_DA No
 OUTFALL_ID ARD-21
 OUTFALL_TY Open Drainage
 PHOTO1 ARD-21A.JPG
 PHOTO2 ARD-21B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Box
 STD_DEV0.613408
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.2

AZ22

73°50'47.347"W 41°1'2.601"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 672471.74
 FID 21
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 120.635
 GPS_TIME 09:38:13am
 HORZ_PREC 1.8
 HyI ..\data\photos\ARD-22A.JPG
 HyII ..\data\photos\ARD-22B.JPG
 Hyper ..\photos\ARD-22A.JPG
 HyperII ..\photos\ARD-22B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-22A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 5.5
 NORTHING 796202.628
 OUTFALL_DA No
 OUTFALL_ID ARD-22
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-22A.JPG
 PHOTO2 ARD-22B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV 1.077963
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 2.6

AZ23

73°50'45.909"W 41°1'6.823"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 36X36X12
 EASTING 672555.728
 FID 22
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 130.121
 GPS_TIME 09:45:59am
 HORZ_PREC 2.5
 HyI ..\data\photos\ARD-23A.JPG
 HyII ..\data\photos\ARD-23B.JPG
 Hyper ..\photos\ARD-23A.JPG
 HyperII ..\photos\ARD-23B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-23A.JPG
 LAND_USE_A Open Space
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 9.4
 NORTHING 796636.429
 OUTFALL_DA No
 OUTFALL_ID ARD-23
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-23A.JPG
 PHOTO2 ARD-23B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Box
 STD_DEV 5.974122
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 0.8

AZ24

73°50'46.181"W 41°1'7.53"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 48X48X6
 EASTING 672555.101
 FID 23
 FLOW_DESCR Substantial
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 128.746
 GPS_TIME 09:50:35am
 HORZ_PREC 5.1
 HyI ..\data\photos\ARD-24A.JPG
 HyII ..\data\photos\ARD-24B.JPG
 Hyper ..\photos\ARD-24A.JPG
 HyperII ..\photos\ARD-24B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-24A.JPG
 LAND_USE_A Open Space
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL Earthen
 MAX_PDOP 8.3
 NORTHING 796694.172
 OUTFALL_DA No
 OUTFALL_ID ARD-24
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-24A.JPG
 PHOTO2 ARD-24B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Box
 STD_DEV 1.814569
 SUBMERGED Water Fully
 UPDATE_STA New
 VERT_PREC 5.1

AZ25

73°50'39.396"W 41°1'6.434"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 673076.034
 FID 24
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 138.733
 GPS_TIME 10:05:19am
 HORZ_PREC 1.3
 HyI ..\data\photos\ARD-25A.JPG
 HyII ..\data\photos\ARD-25B.JPG
 Hyper ..\photos\ARD-25A.JPG
 HyperII ..\photos\ARD-25B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-25A.JPG
 LAND_USE_A Open Space
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL CMP
 MAX_PDOP 6.3
 NORTHING 796587.117
 OUTFALL_DA No
 OUTFALL_ID ARD-25
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-25A.JPG
 PHOTO2 ARD-25B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.290753
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 2.7

AZ26

73°50'44.305"W 41°1'9"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS OUTLET DETENTION POND NOT
 ACCE
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION
 EASTING 672816.378
 FID 25
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 146.836
 GPS_TIME 10:11:56am
 HORZ_PREC 1.6
 HyI ..\data\photos\ARD-26A.JPG
 HyII ..\data\photos\
 Hyper ..\photos\ARD-26A.JPG
 HyperII ..\photos\
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-26A.JPG
 LAND_USE_A Open Space
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL
 MAX_PDOP 5.7
 NORTHING 796799.391
 OUTFALL_DA No
 OUTFALL_ID ARD-26
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-26A.JPG
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1
 STD_DEV1.446303
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1

AZ27

73°50'38.202"W 41°1'14.253"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS COVERED ROCKS NOT ACCESSIBLE
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 673124.552
 FID 26
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 165.87
 GPS_TIME 10:24:12am
 HORZ_PREC 1.3
 HyI ..\data\photos\
 HyII ..\data\photos\
 Hyper ..\photos\
 HyperII ..\photos\
 Hyperlink
 LAND_USE_A Commercial
 Location
 MATERIAL RCP
 MAX_PDOP 4.7
 NORTHING 797375.279
 OUTFALL_DA No
 OUTFALL_ID ARD-27
 OUTFALL_TY Closed Pipe
 PHOTO1
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.10871
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.5

AZ28

73°50'39.562"W 41°1'17.857"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 673078.332
 FID 27
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 165.772
 GPS_TIME 10:30:12am
 HORZ_PREC 1.1
 HyI ..\data\photos\ARD-28A.JPG
 HyII ..\data\photos\ARD-28B.JPG
 Hyper ..\photos\ARD-28A.JPG
 HyperII ..\photos\ARD-28B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-28A.JPG
 LAND_USE_A Commercial
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 2.5
 NORTHING 797747.388
 OUTFALL_DA Spalling,Crack,Chip
 OUTFALL_ID ARD-28
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-28A.JPG
 PHOTO2 ARD-28B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.312128
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.8

AZ29

73°50'39.969"W 41°0'55.616"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 673042.323
 FID 28
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 202.059
 GPS_TIME 11:16:46am
 HORZ_PREC 1.5
 HyI ..\data\photos\ARD-29A.JPG
 HyII ..\data\photos\ARD-29B.JPG
 Hyper ..\photos\ARD-29A.JPG
 HyperII ..\photos\ARD-29B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-29A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 5.2
 NORTHING 795514.586
 OUTFALL_DA No
 OUTFALL_ID ARD-29
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-29A.JPG
 PHOTO2 ARD-29B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.765626
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 0.8

AZ30

73°50'38.879"W 41°0'45.29"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 48
 EASTING 673122.629
 FID 29
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 166.157
 GPS_TIME 11:23:44am
 HORZ_PREC 1.3
 HyI ..\data\photos\ARD-30A.JPG
 HyII ..\data\photos\ARD-30B.JPG
 Hyper ..\photos\ARD-30A.JPG
 HyperII ..\photos\ARD-30B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-30A.JPG
 LAND_USE_A Open Space
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 1.7
 NORTHING 794443.635
 OUTFALL_DA No
 OUTFALL_ID ARD-30
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-30A.JPG
 PHOTO2 ARD-30B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.518457
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.6

AZ31

73°49'58.071"W 41°1'7.003"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS INTO DETENTION POND
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 676228.369
 FID 30
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 358.614
 GPS_TIME 12:16:36pm
 HORZ_PREC 2.5
 HyI ..\data\photos\ARD-31A.JPG
 HyII ..\data\photos\ARD-31B.JPG
 Hyper ..\photos\ARD-31A.JPG
 HyperII ..\photos\ARD-31B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-31A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 9.9
 NORTHING 796664.716
 OUTFALL_DA No
 OUTFALL_ID ARD-31
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-31A.JPG
 PHOTO2 ARD-31B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Double
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.243512
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 8

AZ32

73°49'56.049"W 41°1'5.361"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS OUTLET OF DETENTION POND
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 12X12X12
 EASTING 676388.387
 FID 31
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 343.961
 GPS_TIME 12:24:41pm
 HORZ_PREC 1.8
 HyI ..\data\photos\ARD-32A.JPG
 HyII ..\data\photos\ARD-32B.JPG
 Hyper ..\photos\ARD-32A.JPG
 HyperII ..\photos\ARD-32B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-32A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL Concrete
 MAX_PDOP 7.5
 NORTHING 796491.067
 OUTFALL_DA No
 OUTFALL_ID ARD-32
 OUTFALL_TY Open Drainage
 PHOTO1 ARD-32A.JPG
 PHOTO2 ARD-32B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Box
 STD_DEV1.138382
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.6

AZ33

73°49'36.47"W 41°1'4.047"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 677880.996
 FID 32
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 269.292
 GPS_TIME 12:41:21pm
 HORZ_PREC 2.9
 HyI ..\data\photos\ARD-33A.JPG
 HyII ..\data\photos\ARD-33B.JPG
 Hyper ..\photos\ARD-33A.JPG
 HyperII ..\photos\ARD-33B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-33A.JPG
 LAND_USE_A Open Space
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL CMP
 MAX_PDOP 6.5
 NORTHING 796371.457
 OUTFALL_DA No
 OUTFALL_ID ARD-33
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-33A.JPG
 PHOTO2 ARD-33B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.500087
 SUBMERGED Water Partially
 UPDATE_STA New
 VERT_PREC 4.4

AZ34

73°50'7.253"W 41°0'33.157"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 675562.699
 FID 33
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/23/2006
 GPS_HEIGHT 220.948
 GPS_TIME 01:04:55pm
 HORZ_PREC 2.2
 HyI ..\data\photos\ARD-34A.JPG
 HyII ..\data\photos\ARD-34B.JPG
 Hyper ..\photos\ARD-34A.JPG
 HyperII ..\photos\ARD-34B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-34A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL CMP
 MAX_PDOP 5.6
 NORTHING 793238.475
 OUTFALL_DA No
 OUTFALL_ID ARD-34
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-34A.JPG
 PHOTO2 ARD-34B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV 8.843971
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 0.7

AZ35

73°50'2.168"W 41°0'43.335"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS CLOGGED
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 675945.428
 FID 34
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 281.594
 GPS_TIME 01:16:23pm
 HORZ_PREC 1.7
 HyI ..\data\photos\ARD-35A.JPG
 HyII ..\data\photos\ARD-35B.JPG
 Hyper ..\photos\ARD-35A.JPG
 HyperII ..\photos\ARD-35B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-35A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 5.8
 NORTHING 794266.329
 OUTFALL_DA No
 OUTFALL_ID ARD-35
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-35A.JPG
 PHOTO2 ARD-35B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV 6.271848
 SUBMERGED Sediment Partially
 UPDATE_STA New
 VERT_PREC 1.6

AZ36

73°49'58.42"W 41°0'44.428"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 676213.583
 FID 35
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 301.072
 GPS_TIME 01:27:05pm
 HORZ_PREC 2
 HyI ..\data\photos\ARD-36A.JPG
 HyII ..\data\photos\ARD-36B.JPG
 Hyper ..\photos\ARD-36A.JPG
 HyperII ..\photos\ARD-36B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-36A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL CMP
 MAX_PDOP 4.8
 NORTHING 794381.439
 OUTFALL_DA No
 OUTFALL_ID ARD-36
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-36A.JPG
 PHOTO2 ARD-36B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV 0.980645
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 3.9

AZ37

73°50'13.733"W 41°0'30.621"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 675065.981
 FID 36
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 197.503
 GPS_TIME 01:43:06pm
 HORZ_PREC 1.9
 HyI ..\data\photos\ARD-37A.JPG
 HyII ..\data\photos\ARD-37B.JPG
 Hyper ..\photos\ARD-37A.JPG
 HyperII ..\photos\ARD-37B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-37A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 4.8
 NORTHING 792976.674
 OUTFALL_DA No
 OUTFALL_ID ARD-37
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-37A.JPG
 PHOTO2 ARD-37B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV 4.300023
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.3

AZ38

73°50'7.589"W 41°0'56.104"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 675518.016
 FID 37
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/23/2006
 GPS_HEIGHT 362.136
 GPS_TIME 02:02:41pm
 HORZ_PREC 2.2
 HyI ..\data\photos\ARD-38A.JPG
 HyII ..\data\photos\ARD-38B.JPG
 Hyper ..\photos\ARD-38A.JPG
 HyperII ..\photos\ARD-38B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-38A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 8
 NORTHING 795553.258
 OUTFALL_DA No
 OUTFALL_ID ARD-38
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-38A.JPG
 PHOTO2 ARD-38B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1
 STD_DEV 23.175294
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1

AZ39

73°50'1.198"W 41°0'27.238"N
 ABNORMAL_V Inhibited
 CHARACTERI Suspect
 COMMENTS PIPE COULD NOT BE LOCATED
 CLOG
 CORR_TYPE Postprocessed Code
 DEPOSITS_S Oily
 DIMENSION
 EASTING 676000.273
 FID 38
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 188.102
 GPS_TIME 07:05:37am
 HORZ_PREC 1.9
 HyI ..\data\photos\
 HyII ..\data\photos\
 Hyper ..\photos\
 HyperII ..\photos\
 Hyperlink
 LAND_USE_A Institutional
 Location
 MATERIAL
 MAX_PDOP 4.5
 NORTHING 792643.776
 OUTFALL_DA No
 OUTFALL_ID ARD-39
 OUTFALL_TY Closed Pipe
 PHOTO1
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ Oil Sheen
 QUANTITY Single
 Shape Point
 SHAPE_1
 STD_DEV 0.386178
 SUBMERGED Water Fully
 UPDATE_STA New
 VERT_PREC 3.3

AZ40

73°50'5.995"W 41°0'23.144"N
 ABNORMAL_V Excessive
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 675664.331
 FID 39
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 172.158
 GPS_TIME 07:13:35am
 HORZ_PREC 1.8
 HyI ..\data\photos\ARD-40A.JPG
 HyII ..\data\photos\ARD-40B.JPG
 Hyper ..\photos\ARD-40A.JPG
 HyperII ..\photos\ARD-40B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-40A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 3.7
 NORTHING 792221.924
 OUTFALL_DA No
 OUTFALL_ID ARD-40
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-40A.JPG
 PHOTO2 ARD-40B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.343357
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.4

AZ41

73°50'7.15"W 41°0'20.921"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 36
 EASTING 675565.109
 FID 40
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/24/2006
 GPS_HEIGHT 186.282
 GPS_TIME 07:20:21am
 HORZ_PREC 1.5
 HyI ..\data\photos\ARD-41A.JPG
 HyII ..\data\photos\ARD-41B.JPG
 Hyper ..\photos\ARD-41A.JPG
 HyperII ..\photos\ARD-41B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-41A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL CMP
 MAX_PDOP 1.8
 NORTHING 792005.368
 OUTFALL_DA No
 OUTFALL_ID ARD-41
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-41A.JPG
 PHOTO2 ARD-41B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.56422
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.1

AZ42

73°50'7.541"W 41°0'15.742"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 675518.331
 FID 41
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/24/2006
 GPS_HEIGHT 178.902
 GPS_TIME 07:27:06am
 HORZ_PREC 1.3
 HyI ..\data\photos\ARD-42A.JPG
 HyII ..\data\photos\ARD-42B.JPG
 Hyper ..\photos\ARD-42A.JPG
 HyperII ..\photos\ARD-42B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-42A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 3.4
 NORTHING 791461.884
 OUTFALL_DA No
 OUTFALL_ID ARD-42
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-42A.JPG
 PHOTO2 ARD-42B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ Excessive Algae
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.646194
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.4

AZ43

73°50'7.985"W 41°0'15.656"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING
 FID 41
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/24/2006
 GPS_HEIGHT
 GPS_TIME
 HORZ_PREC
 HyI ..\data\photos\ARD-43A.JPG
 HyII ..\data\photos\ARD-43B.JPG
 Hyper ..\photos\ARD-43A.JPG
 HyperII ..\photos\ARD-43B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-43A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL Corr Metal
 MAX_PDOP
 NORTHING
 OUTFALL_DA No
 OUTFALL_ID ARD-43
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-43A.JPG
 PHOTO2 ARD-43B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC

AZ44

73°50'8.193"W 41°0'15.185"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 30
 EASTING 675518.331
 FID 41
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/24/2006
 GPS_HEIGHT
 GPS_TIME
 HORZ_PREC
 HyI ..\data\photos\ARD-44A.JPG
 HyII ..\data\photos\ARD-44B.JPG
 Hyper ..\photos\ARD-44A.JPG
 HyperII ..\photos\ARD-44B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-44A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL PVC
 MAX_PDOP
 NORTHING
 OUTFALL_DA No
 OUTFALL_ID ARD-44
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-44A.JPG
 PHOTO2 ARD-44B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.4

AZ45

73°50'12.908"W 41°0'11.227"N
 ABNORMAL_V Excessive
 CHARACTERI Unlikely
 COMMENTS COVERED BY ROCKS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 6
 EASTING 675136.759
 FID 42
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 176.757
 GPS_TIME 08:07:01am
 HORZ_PREC 1.4
 HyI ..\data\photos\
 HyII ..\data\photos\
 Hyper ..\photos\
 HyperII ..\photos\
 Hyperlink
 LAND_USE_A Open Space
 Location
 MATERIAL PVC
 MAX_PDOP 5.3
 NORTHING 791011.461
 OUTFALL_DA Spalling,Crack,Chip
 OUTFALL_ID ARD-45
 OUTFALL_TY Closed Pipe
 PHOTO1
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.228476
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.1

AZ46

73°49'59.813"W 41°0'41.091"N
 ABNORMAL_V Inhibited
 CHARACTERI Unlikely
 COMMENTS COVERED BY BUSHES NOT
 ACCESSIB
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 676126.388
 FID 43
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 264.174
 GPS_TIME 08:25:47am
 HORZ_PREC 2.9
 HyI ..\data\photos\
 HyII ..\data\photos\
 Hyper ..\photos\
 HyperII ..\photos\
 Hyperlink
 LAND_USE_A Suburban Res
 Location
 MATERIAL RCP
 MAX_PDOP 8
 NORTHING 794034.287
 OUTFALL_DA No
 OUTFALL_ID ARD-46
 OUTFALL_TY Closed Pipe
 PHOTO1
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.953774
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 6

AZ47

73°50'10.637"W 41°0'57.065"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 15
 EASTING 675280.544
 FID 44
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 362.435
 GPS_TIME 08:34:49am
 HORZ_PREC 1.2
 HyI ..\data\photos\ARD-47A.JPG
 HyII ..\data\photos\ARD-47B.JPG
 Hyper ..\photos\ARD-47A.JPG
 HyperII ..\photos\ARD-47B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-47A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL PVC
 MAX_PDOP 1.6
 NORTHING 795664.965
 OUTFALL_DA No
 OUTFALL_ID ARD-47
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-47A.JPG
 PHOTO2 ARD-47B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.158789
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 0.9

AZ48

73°50'25.632"W 41°1'3.187"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS 3 OUTFALLS TOGETHER
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 674116.51
 FID 45
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 307.089
 GPS_TIME 08:46:22am
 HORZ_PREC 2.7
 HyI ..\data\photos\ARD-48A.JPG
 HyII ..\data\photos\ARD-48B.JPG
 Hyper ..\photos\ARD-48A.JPG
 HyperII ..\photos\ARD-48B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-48A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 9.1
 NORTHING 796279.165
 OUTFALL_DA No
 OUTFALL_ID ARD-48
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-48A.JPG
 PHOTO2 ARD-48B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.838023
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 7

AZ49

73°50'25.634"W 41°1'3.155"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS 3 OUTFALLS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 30
 EASTING 674116.379
 FID 46
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/24/2006
 GPS_HEIGHT 301.239
 GPS_TIME 08:47:57am
 HORZ_PREC 2.6
 HyI ..\data\photos\ARD-49A.JPG
 HyII ..\data\photos\ARD-49B.JPG
 Hyper ..\photos\ARD-49A.JPG
 HyperII ..\photos\ARD-49B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-49A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 9.1
 NORTHING 796273.909
 OUTFALL_DA No
 OUTFALL_ID ARD-49
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-49A.JPG
 PHOTO2 ARD-49B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.368438
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 6.6

AZ50

73°50'25.712"W 41°1'3.119"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 36
 EASTING 674112.216
 FID 47
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 320.148
 GPS_TIME 08:49:03am
 HORZ_PREC 2.3
 HyI ..\data\photos\ARD-50A.JPG
 HyII ..\data\photos\ARD-50B.JPG
 Hyper ..\photos\ARD-50A.JPG
 HyperII ..\photos\ARD-50B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-50A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 8
 NORTHING 796270.375
 OUTFALL_DA No
 OUTFALL_ID ARD-50
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-50A.JPG
 PHOTO2 ARD-50B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.277951
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 0.9

AZ51

73°50'29.168"W 41°1'5.284"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 48
 EASTING 673856.215
 FID 48
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/24/2006
 GPS_HEIGHT 293.279
 GPS_TIME 08:53:22am
 HORZ_PREC 1.6
 HyI ..\data\photos\ARD-51A.JPG
 HyII ..\data\photos\ARD-51B.JPG
 Hyper ..\photos\ARD-51A.JPG
 HyperII ..\photos\ARD-51B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-51A.JPG
 LAND_USE_A Institutional
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 4
 NORTHING 796491.184
 OUTFALL_DA No
 OUTFALL_ID ARD-51
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-51A.JPG
 PHOTO2 ARD-51B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV1.339528
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.1

AZ52

73°50'32.709"W 41°1'4.952"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 12
 EASTING 673576.688
 FID 49
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 261.512
 GPS_TIME 08:57:49am
 HORZ_PREC 2.5
 HyI ..\data\photos\ARD-52A.JPG
 HyII ..\data\photos\
 Hyper ..\photos\ARD-52A.JPG
 HyperII ..\photos\
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-52A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL CMP
 MAX_PDOP 9.1
 NORTHING 796435.466
 OUTFALL_DA No
 OUTFALL_ID ARD-52
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-52A.JPG
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.995609
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 5.7

AZ53

73°50'50.191"W 41°0'30.02"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 15
 EASTING 672261.893
 FID 50
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 244.4
 GPS_TIME 10:03:49am
 HORZ_PREC 2.3
 HyI ..\data\photos\ARD-53A.JPG
 HyII ..\data\photos\ARD-53B.JPG
 Hyper ..\photos\ARD-53A.JPG
 HyperII ..\photos\ARD-53B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-53A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL CMP
 MAX_PDOP 7
 NORTHING 792908.814
 OUTFALL_DA No
 OUTFALL_ID ARD-53
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-53A.JPG
 PHOTO2 ARD-53B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV0.863864
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 4.6

AZ54

73°50'50.244"W 41°0'29.798"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 36
 EASTING 672266.201
 FID 51
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/24/2006
 GPS_HEIGHT 243.297
 GPS_TIME 10:04:58am
 HORZ_PREC 1.8
 HyI ..\data\photos\ARD-54A.JPG
 HyII ..\data\photos\ARD-54B.JPG
 Hyper ..\photos\ARD-54A.JPG
 HyperII ..\photos\ARD-54B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-54A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL CMP
 MAX_PDOP 6.3
 NORTHING 792896.028
 OUTFALL_DA No
 OUTFALL_ID ARD-54
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-54A.JPG
 PHOTO2 ARD-54B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV2.409371
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 0.8

AZ55

73°51'3.103"W 41°0'26.274"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS GOES UNDER THRUWAY
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 12
 EASTING 671274.143
 FID 52
 FLOW_DESCR
 FLOW_PRESE No
 GPS_DATE 10/24/2006
 GPS_HEIGHT 141.769
 GPS_TIME 10:39:56am
 HORZ_PREC 1.7
 HyI ..\data\photos\ARD-55A.JPG
 HyII ..\data\photos\ARD-55B.JPG
 Hyper ..\photos\ARD-55A.JPG
 HyperII ..\photos\ARD-55B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-55A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 4
 NORTHING 792517.406
 OUTFALL_DA No
 OUTFALL_ID ARD-55
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-55A.JPG
 PHOTO2 ARD-55B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV 3.288794
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.4

AZ56

73°51'3.056"W 41°0'26.428"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS GOES UNDER THRUWAY
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 12
 EASTING 671274.345
 FID 53
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE 10/24/2006
 GPS_HEIGHT 141.98
 GPS_TIME 10:43:24am
 HORZ_PREC 1.8
 HyI ..\data\photos\ARD-56A.JPG
 HyII ..\data\photos\
 Hyper ..\photos\ARD-56A.JPG
 HyperII ..\photos\
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-56A.JPG
 LAND_USE_A Suburban Res
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 4
 NORTHING 792533.486
 OUTFALL_DA No
 OUTFALL_ID ARD-56
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-56A.JPG
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV 1.7411
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC 1.3

AZ57

73°51'9.958"W 41°0'28.107"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 15
 EASTING 670748.935
 FID 54
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE 10/24/2006
 GPS_HEIGHT 120.912
 GPS_TIME 10:55:52am
 HORZ_PREC 1.5
 HyI ..\data\photos\ARD-57A.JPG
 HyII ..\data\photos\ARD-57B.JPG
 Hyper ..\photos\ARD-57A.JPG
 HyperII ..\photos\ARD-57B.JPG
 Hyperlink M:\aeh2\Outfalls\Photos\ARD-57A.JPG
 LAND_USE_A
 Location M:\aeh2\Outfalls\Photos\
 MATERIAL RCP
 MAX_PDOP 5
 NORTHING 792706.806
 OUTFALL_DA Spalling,Crack,Chip
 OUTFALL_ID ARD-57
 OUTFALL_TY Closed Pipe
 PHOTO1 ARD-57A.JPG
 PHOTO2 ARD-57B.JPG
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV 0.473743
 SUBMERGED Water Fully
 UPDATE_STA New
 VERT_PREC 3.4

AZ58

73°49'44.85"W 41°1'0.886"N
 ABNORMAL_V Excessive
 CHARACTERI Unlikely
 COMMENTS
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 15
 EASTING 677243.72
 FID
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE
 GPS_HEIGHT
 GPS_TIME
 HORZ_PREC
 HyI
 HyII
 Hyper
 HyperII
 Hyperlink
 LAND_USE_A Suburban Res
 Location
 MATERIAL PVC
 MAX_PDOP
 NORTHING 796069.32
 OUTFALL_DA No
 OUTFALL_ID OF 30
 OUTFALL_TY Closed Pipe
 PHOTO1 OF 30
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC

AZ59

73°50'39.827"W 41°1'4.151"N
 ABNORMAL_V No
 CHARACTERI Unlikely
 COMMENTS GOES UNDER ROUTE 9A
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 24
 EASTING 673027.26
 FID
 FLOW_DESCR Moderate
 FLOW_PRESE Yes
 GPS_DATE
 GPS_HEIGHT
 GPS_TIME
 HORZ_PREC
 HyI
 HyII
 Hyper
 HyperII
 Hyperlink
 LAND_USE_A Suburban Res
 Location
 MATERIAL Metal
 MAX_PDOP
 NORTHING 796367.68
 OUTFALL_DA No
 OUTFALL_ID OF 158
 OUTFALL_TY Closed Pipe
 PHOTO1 OF 158
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC

AZ60

73°50'15.136"W 41°0'8.923"N
 ABNORMAL_V Excessive
 CHARACTERI Unlikely
 COMMENTS DISSIPATOR PAN
 CORR_TYPE Postprocessed Code
 DEPOSITS_S No
 DIMENSION 18
 EASTING 674962.25
 FID
 FLOW_DESCR Trickle
 FLOW_PRESE Yes
 GPS_DATE
 GPS_HEIGHT
 GPS_TIME
 HORZ_PREC
 HyI
 HyII
 Hyper
 HyperII
 Hyperlink
 LAND_USE_A Open Space
 Location
 MATERIAL Metal
 MAX_PDOP
 NORTHING 790792.92
 OUTFALL_DA Rust
 OUTFALL_ID OF 183
 OUTFALL_TY Closed Pipe
 PHOTO1 OF 183
 PHOTO2
 PHOTO3
 PIPE_BENTH No
 POOR_POOL_ No
 QUANTITY Single
 Shape Point
 SHAPE_1 Circular
 STD_DEV
 SUBMERGED No
 UPDATE_STA New
 VERT_PREC

AZ61

73°50'42.748"W 41°1'15.28"N

ABNORMAL_V	No
CHARACTERI	Unlikely
COMMENTS	BIORETENTION OUTLET
CORR_TYPE	Postprocessed Code
DEPOSITS_S	No
DIMENSION	30
EASTING	672794.98
FID	
FLOW_DESCR	Moderate
FLOW_PRESE	Yes
GPS_DATE	
GPS_HEIGHT	
GPS_TIME	
HORZ_PREC	
HyI	
HyII	
Hyper	
HyperII	
Hyperlink	
LAND_USE_A	Open Space
Location	
MATERIAL	Metal
MAX_PDOP	
NORTHING	797492.29
OUTFALL_DA	No
OUTFALL_ID	OF 184
OUTFALL_TY	Closed Pipe
PHOTO1	OF 184
PHOTO2	
PHOTO3	
PIPE_BENTH	No
POOR_POOL_	No
QUANTITY	Single
Shape	Point
SHAPE_1	Circular
STD_DEV	
SUBMERGED	Partially
UPDATE_STA	New
VERT_PREC	